

Apartment Building Evaluation Summary

Mississauga Apartment Rental Compliance
(MARC)



Transportation & Works Department
Compliance & Licensing Enforcement
300 City Centre Drive
Mississauga, Ontario, L5B 3C1
Tel: 905-615-4311
marc.registration@mississauga.ca
mississauga.ca/MARC

Building Address: 1219 DUNDAS ST W	SCORE: 88%
Enforcement Officer: Ron Maginnis	
Date of Evaluation: January 25, 2023	Next Evaluation: January 2025

Exterior	Condition
Grounds – e.g., walkways, parking area, landscaping	Good
Amenities – e.g., playground, swimming pool, patio	Not Evaluated
Building – e.g., walls, windows, doors	Very Good
Roof	Very Good

Interior Common Areas	Condition
Lobby	Very Good
Elevators	Very Good
Stairwells	Very Good
Hallways	Good
Mechanical & Service Rooms	Good
Storage & Locker Rooms	Not Evaluated
Washrooms & Laundry Room	Very Good
Amenities – e.g., party room, swimming pool, exercise room	Not Evaluated
Refuse Storage Room	Good
Parking Garage	Very Good

Administrative	Condition
Tenant Notification Board	Good
Procedures – e.g., tenant service requests, pest management	Good
Plans – e.g., cleaning, waste management, state of good repair	Good
Records – e.g., stored securely and accessible	Good

Note:

This is a summary of the Evaluation results. You may contact a representative from your apartment building to request a copy of the complete Evaluation.



For more information about the MARC Program scan QR code, call 311, or visit mississauga.ca/MARC